Attachment A: Texas Instruments PowerPoint Presentations to EPA, June 24 and July 17, 2020

Texas Instruments NPDES Permit Renewal Letter to EPA Region 1

August 14, 2020


Texas Instruments, Attleboro, MA NPDES Permit

June 2020 conference call with EPA

- 1. Overview of MCP Site
- 2. Overview of NPDES Permit
- 3. Summary of TCE Exceedances and Responses
- 4. On-going and Planned Evaluations to Improve System

1.) Massachusetts Contingency Plan (MCP) Site Overview

- MassDEP MCP RTN 4-0022; currently has a Temporary Solution
- Since 1986, a groundwater extraction system located south of Building 3 has operated to recover contaminated groundwater for treatment.
- In 2013 a new treatment system was constructed to replace the original treatment system, and the recovery system was expanded to include collection and treatment of dry weather flow (seepage of groundwater into the subsurface storm drain system).



Site Plan - MCP Site

MCP Site Overview (continued)


- 6-month Temporary Solution Status Reports are submitted to MassDEP per MCP. Every 5 years, a review of the Temporary Solution is completed per the MCP.
- On-going MCP assessment continuing at parts of the site with reporting to MassDEP.
- Site property is no longer owned or occupied by TI and TI is considered a former owner and operator. In 2005, Preferred Real Estate Investments, Inc. (PREI), the entity that purchased the property from TI, submitted an application to the Massachusetts Attorney General's Office for protection from MCP liability under the Brownfields Covenant-not-to-Sue program. The property that makes up the site is currently owned by various entities, and PREI no longer owns any of the property.

2.) Overview of NPDES Permit and History


Outfalls in MA0001791(1986-present)

- 002A GWTP discharge (treated GW from RTN 4-0022 remediation system for TCE plume) plus subsurface storm drain dry weather flow (GW infiltration) leaving site just north of RR tracks and entering city of Attleboro storm sewer system
 - Prior to Nov 2013 dry weather flow not collected/treated
 - Nov 2013-present dry weather flow collected/treated along with extracted GW
- 002B GWTP discharge (treated GW)
- 004 storm drain flow (including GW infiltration) from eastern part of campus (area where TCE plume is attenuating naturally)
- 007 outlet of Coopers Pond (TI historic discharge to pond ended in 2000; pond sediment is MCP RTN 4-21862, COCs are metals, temporary solution in place since 2012 that monitors pond)
- TI submitted a request to eliminate 007 from the permit as part of its permit application 2015.


Outfall and Facility Locations



Storm Drain and Groundwater Collection Systems



Stormwater Runoff (During Storm Events ONLY)



Overview of NPDES Permit and History (cont.)

	Current Permit (October 2010)			
Outfall	Monitoring Frequency	Analytes	Limit/Requirement	
002A (GWTP discharge plus dry weather flow)	Monthly	TCE	5	
		Cis-1,2-DCE	70	
		Vinyl Chloride, PCE	Report monthly	
		рН	6.5 - 8.3	
002B (GWTP discharge)	Monthly	TCE	5	
		Trans-1,2-DCE	100	
		рН	6.5 - 8.3	
004 (dry weather flow, eastern area)	Monthly	TCE; cis-1,2-DCE	Report monthly	
		PCE, Vinyl Chloride, Chloroform	Report quarterly	
		рН	6.5 - 8.3	
007 (Coopers Pond outlet)	Quarterly	pH, AI, Cu, Pb, Ni, Ag, Zn	Report Quarterly	

Schematic of Water Flow: Outfalls 002A and 002B



Flow in excess of dry weather flow (overflow from collection structure)

Schematic of Water Flow: Outfall 004

Subsurface Storm Drain System

Groundwater Infiltration
(92,000 GPD average)
Plus sources of waters sampling point
(e.g., stormwater, snow, melt) not regulated under this permit



Outfall 004 flow rate is based on average of monthly measurements from December 2018 – May 2020. These measurements are performed once a month during dry weather as specified in the permit.

Overview of NPDES Permit and History (continued)

- October 2010 Permit: limits set for TCE, other cVOCs in 002A (had been "report monthly")
 - 2011 storm drains cleaned and video inspected to determine if GW infiltration could be sufficiently prevented to meet 002A limits in short term; conclusion was no. Data collection to support new system design to collect and treat dry weather flow begins.
 - February 2012 EPA issues Administrative Order with conditions/schedule for complying with new limits (construction of new dry weather flow collection system/GWTP)
 - May 2012 system design submitted to EPA
 - October 2012 TI obtains agreement with property owner to construct new system
 - April October 2013: new GWTP with dry weather flow collection under construction
 - November 2013 new system becomes operational
 - June 2015 permit application submitted (includes request to eliminate 007)

Overview of NPDES Permit and History (continued)


 The monthly monitoring requirements and permit limits from the March 2000 and October 2010 permits for 002B and 002A are summarized below. TCE drops to 5 ppb. New GWTP (tray air stripper, GAC polishing) designed for this value.

Outfall	Compound	Former Requirement or Limit (March 2000) (ppb)	New Limit (October 2010) (ppb)
002B (treatment system effluent)	trans-1,2- Dichloroethene	100	100
	TCE	100	5
	Chloroform	100	None
	рН	6.5-8.3	6.5-8.3
002A (dry weather flow from subsurface storm drain system)	cis-1,2-Dichloroethene	Report monthly	70
	TCE	Report monthly	5
	Vinyl Chloride	Report monthly	Report monthly
	Tetrachloroethylene	Report monthly	Report monthly
	Chloroform	Report monthly	None
	Methyl-tert-butyl ether	Report monthly	None
	рН	6.5-8.3	6.5-8.3

Overview of NPDES Permit and History (continued)

- The dry-weather flow collection system and new GWTP were designed to meet the October 2010 permit limits. Construction of the new system began in June 2013 and was completed in October 2013. The new system underwent testing and commissioning activities beginning in October before it was put into full operation in mid-November 2013.
- The average influent flow rates to the system since startup:
 - > Overburden 30 gpm
 - ➤ Bedrock 15 gpm
 - ➤ Dry Weather Flow Collection Vault 34 gpm

Treatment System Diagram - Layout



Note: This is the original layout from 2013 and does not include modifications made since then

GWTP Building

Aerial view - Influent tank, Control Room and Air Stripper visible



Control Room



Bag Filter skid



Carbon Vessels



Air Stripper skid



Backwash Tank



Stormwater Pre-Filtration System



3.) Summary of Exceedance of TCE Permit Limit at Outfall 002A

- 79 sampling events and 31 exceedances between November 2013 and April 2020. May 2020 results were non-detect.
- Exceedances ranged from 5.4 ug/l to 60.8 ug/l (12 exceedances 10 ug/l or less). Exceedances have decreased in magnitude and frequency over time.
- Common reasons for exceedances:
 - ➤ Bacterial fouling of various system components;
 - ➤ Clog in storm drain system downstream of outfall 002A causing backup into collection system; and,
 - ➤ Insufficient capture of dry weather flow.

Summary of Exceedance of TCE Permit Limit at Outfall 002A (continued)

- Corrective Actions Implemented since 2014:
 - > Downstream drain cleaning to remove clog (2014);
 - > Stormwater influent line cleaning with acid wash (2014, 2015);
 - > Float switch and pump repairs/replacements (2016 2020);
 - ➤ Catch basin bottom sealings (2017);
 - ➤ Addition of pre-filtration of dry-weather flow (2018);
 - ➤ Replacement of CB-88 (2019);
 - Adjustment of overburden and storm sewer systems recovery flow rates (2017 2020);
 - Adjustments of level setpoints to ensure complete capture of dry-weather flow (2018 2020); and,
 - ➤ Cleaned effluent discharge pipe (2018 2020).

Catch Basin Sealing (DMH-D in Building 3)

Pre-Sealing



1 day Post-Sealing



3 days Post-Sealing




4.) On-going and Planned Storm Sewer and Recovery System Evaluation and Maintenance (2020)

- Storm sewer line (DMH-F) cleanout June 2020.
- Catch basin sealing effectiveness testing June/July 2020.
- Flow measurement work on-going (continuation from 2019 studies):
 - Investigating groundwater infiltration to the subsurface storm water drainage system in the vicinity of the recovery and treatment system, to identify potential sources of significant infiltration, and to develop a strategy for improving the combined storm and groundwater recovery and treatment system efficiency.
- Overburden recovery system header pipe cleanouts June/July 2020.

Example Storm Sewer Profile from 2019 Study

(depicting elevations, water levels and TCE results)





Discussion and Contact Information

Joe Bauer, P.G.

Director, Environmental Assessments and Remediation

Texas Instruments Incorporated

Worldwide Environmental, Safety, & Health

Dallas, Texas

(214) 567-4874 (office)

jbauer@ti.com

Kai Williams

Specialist, Environmental Assessments and Remediation

Texas Instruments Incorporated

Worldwide Environmental. Safety, & Health

Dallas, Texas

(214) 479-8291 (office)

k-williams@ti.com

David G. Austin, LSP, LEP, PG

AECOM

250 Apollo Drive

Chelmsford, Massachusetts 01824

(978) 905-2114 (office)

david.austin@aecom.com


Attleboro Site -NPDES Outfall 002A Exceedances

Texas Instruments


Under Normal Operating Conditions

- Treating Bedrock, Overburden, Groundwater Infiltration (GWI) at Groundwater Treatment Plant (GWTP)
 - 40 gpm is representative of full capture of contaminated groundwater infiltrating the storm sewer during dry weather conditions
- Treated water from GWTP exits 002B (below permit limits) and goes to 002A
- No exceedances at 002A

Under Normal Operating Conditions



Under Normal Operating Conditions



GWTP = Groundwater Treatment Plant


Under Storm Conditions

- Treating water from Bedrock, Overburden, Groundwater Infiltration (GWI), and Site Runoff
- Site runoff enters sewer and mixes with infiltrated contaminated groundwater
 - Flow above 40 gpm not captured
 - Mixed flow going over the baffle can contain TCE above permit limits and goes to 002A without being treated
 - Site runoff does not dilute GWI enough to be below permit limits which leads to exceedances


Under Storm Conditions (continued)

- System baffle causes runoff from storm events to accumulate or retained upstream
- The accumulated runoff can take longer than 48 hours to completely dissipate and the collection system return to normal operating (permit) conditions

Under Storm Conditions



Under Storm Conditions



RO = Runoff

SS = Storm Sewer Influent to GWTP

Storm Sewer Flow & Outfall Exceedances

	Flow Recovered (gpm)	Flow Over Baffle (gpm)	002A Outfall TCE Conc. (ppb)
June 2020	38	0	2.3
October 2018	43	3.9	7.6
August 2018	32	6	10
January 2019	49.6	8-28	18
April 2019	44.6	22-30	39

TCE permit exceedances seen at 002A when storm events cause site runoff to enter storm sewer collection system and cause untreated water to go over the baffle wall

NPDES Permit (MA0001791)

- "...Such discharges shall be limited and monitored by the permittee as specified below and apply during dry weather conditions, defined as any time when there is no precipitation and that is at least 48 hours after a storm event that was greater than 0.1 inches in magnitude."
- In months of high precipitation 48 hours might not be enough for the system to return to normal operating conditions and get a representative sample during a calendar month

Proposed Solution

Include clause in new NPDES permit that extends the 48 hour wait time to apply when normal operating conditions cannot be achieved in a given month due to extended storm conditions (including subsequent runoff) greater than 0.1 inches that prevent representative sampling during dry weather conditions